



JEPPESEN.

NavData® Alert

!! URGENT !!

Date: 17 January 2013

Subject: Mexico
Cancun, Cancun Intl (MMUN)
Cozumel, Cozumel Intl (MMCZ)
Merida, Lic Manuel Crescencio Rejon Intl (MMMD)
Multiple Procedures
Cycle 1301

Outdated Procedure Coding

Jeppesen NavData for cycle 1301, effective 10 Jan 2013, contains outdated procedure coding. Mexico AIP Supplement 1/13 effective 10 JAN 13 was received after the date specified by ICAO for aeronautical information distribution. As a result, changes to procedures listed on the follow page could not be processed for the 10 January 2013 effective date.

THEREFORE, USE CAUTION WHEN USING THE PROCEDURES LISTED ON THE FOLLOWING PAGE IN NAVDATA CYCLE 1301.

Revised coding will appear in Jeppesen NavData for cycle 1302, effective 7 February 2013. Until then an entry will appear in the NavData Change Notices beginning 25 Jan 13, and this Alert will be posted on the Jeppesen Web site (<http://www1.jeppesen.com/company/alerts/aviation-alerts.jsp?region=LatinAmerica>).

WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:

Phone: 1-303-328-4445

E-mail: navdatatechsupport@jeppesen.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. They are distributed to affected ARINC 424 NavData users (avionics companies and other raw data users) and airlines receiving NavData directly from Jeppesen. Alerts are not distributed by Jeppesen to individual airline, business aviation or general aviation pilots, but are available to them on the Jeppesen Web site, www.jeppesen.com. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. Avionics users should consult with their database update service provider for definitive information on whether their system is affected by this Alert.

List of procedures affected by AIP Supplement 1/13.

LOCATION	PROCEDURE	CHANGE
Cancun (MMUN)	BUDAL TWO ALFA [DUBA2A]	Procedure Removed
Cancun (MMUN)	BUDAL TWO BRAVO [DUBA2B]	Procedure Removed
Cancun (MMUN)	EMUSO TWO ALFA [EMUS2A]	Procedure Removed
Cancun (MMUN)	EMUSO TWO BRAVO [EMUS2B]	Procedure Removed
Cancun (MMUN)	ILS DME 3 Rwy 12L [I12L3]	BUDAL Transition Removed LETIS Transition – MEDOX renamed XOPUT
Cancun (MMUN)	ILS DME 3 Rwy 12R [I12R]	BUDAL Transition Removed
Cancun (MMUN)	VOR DME 2 Rwy 12L [D12L]	BUDAL Transition Removed LETIS Transition – MEDOX renamed XOPUT
Cancun (MMUN)	VOR DME 2 Rwy 12R [D12R2]	BUDAL Transition Removed
Cancun (MMUN)	VOR DME 2 Rwy 30L [D30L]	LETIS Transition – MEDOX renamed XOPUT
LOCATION	PROCEDURE	CHANGE
COZUMEL (MMCZ)	VOR DME 2 Rwy 11 [D11]	MIXUN Transition Removed
COZUMEL (MMCZ)	VOR DME 2 Rwy 29 [D29]	SINLA Transition – SINLA renamed ONDEB
LOCATION	PROCEDURE	CHANGE
MERIDA (MMMD)	ILS DME 2 Rwy 10 [I10-2]	TAGNU Transition Removed
MERIDA (MMMD)	VOR DME 2 Rwy 10 [D10-2]	TAGNU Transition Removed
MERIDA (MMMD)	VOR DME 2 Rwy 18 [D18-2]	KUMAN Transition and TAGNU Transition Removed
MERIDA (MMMD)	VOR DME 2 Rwy 28 [D28-2]	KUMAN Transition Removed

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:

Phone: 1-303-328-4445

E-mail: navdatatechsupport@jeppesen.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. They are distributed to affected ARINC 424 NavData users (avionics companies and other raw data users) and airlines receiving NavData directly from Jeppesen. Alerts are not distributed by Jeppesen to individual airline, business aviation or general aviation pilots, but are available to them on the Jeppesen Web site, www.jeppesen.com. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. Avionics users should consult with their database update service provider for definitive information on whether their system is affected by this Alert.