



JEPPESEN.

NavData® Alert

!! URGENT !!

Date: 28 July 2011

Subject: Tawau, Malaysia
Tawau Airport (WBKW)
Approach Procedures
Cycle 1108

Approach Procedures Unusable

Jeppesen NavData for cycle 1108, effective 28 July 2011, contains incorrect Approach Procedure information for the VOR Rwy 06 [D06], VOR Rwy 24 [D24], and ILS or LOC Rwy 24 [I24] for Tawau Airport; Tawau, Malaysia (WBKW).

THEREFORE, DO NOT USE THE APPROACH PROCEDURES LISTED BELOW IN CYCLE 1108 NAVDATA FOR TAWAU AIRPORT (WBKW):

VOR Rwy 06 [D06]
VOR Rwy 24 [D24]
ILS or LOC Rwy 24 [I24]

Revised coding will appear in Jeppesen NavData for cycle 1109, effective 25 August 2011. Until then an entry will appear in the NavData Change Notices beginning 5 AUG 11 revision. This Alert will be posted on the Jeppesen Web site ([http://www.jeppesen.com/company/alerts/aviation-alerts.jsp?region=Pacific Basin](http://www.jeppesen.com/company/alerts/aviation-alerts.jsp?region=Pacific%20Basin)).

Please refer to the Tawau, Malaysia (WBKW) 11-1 ILS or LOC Rwy 24, 13-1 VOR Rwy 06, and 13-2 VOR Rwy 24 charts dated 18 FEB 11 for valid information.

WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:
Phone: 303-328-4445 E-mail: navdatatechsupport@jeppesen.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. They are distributed to affected ARINC 424 NavData users (avionics companies and other raw data users) and airlines receiving NavData directly from Jeppesen. Alerts are not distributed by Jeppesen to individual airline, business aviation or general aviation pilots, but are available to them on the Jeppesen Web site, www.jeppesen.com. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. Avionics users should consult with their database update service provider for definitive information on whether their system is affected by this Alert.