



JEPPESEN.

NavData® Alert

!! URGENT !!

Date: 27 April 2012

Subject: Havana, Cuba
Jose Marti Intl (MUHA)
Manzanillo, Cuba
Sierra Maestra (MUMZ)
Multiple Procedures
Cycle 1205

Outdated Procedure Coding

Jeppesen NavData for cycle 1205, effective 03 May 2012, contains outdated procedure coding. Cuba AIP Amdt 1-12 effective 03 MAY 12 was received after the date specified by ICAO for aeronautical information distribution. As a result, changes to procedures listed below could not be processed for the 03 May12 effective date.

LOCATION	PROCEDURE	CHANGE
Havana (MUHA)	ILS Rwy 06 [I06]	UHA VOR Transition Unusable
Havana (MUHA)	VOR Rwy 06 [D06] or [S06]	Entire Procedure Unusable
Havana (MUHA)	VOR Rwy 24 [D24] or [S24]	UHA VOR Transition Unusable
Havana (MUHA)	NDB Rwy 06 [N06] or [Q06]	UJM NDB Transition Unusable
Manzanillo (MUMZ)	VOR Rwy 08 [D08] or [S08]	Missed Approach Holding Altitude changed to 3000'
Manzanillo (MUMZ)	NDB Rwy 08 [N08] or [Q08]	Procedure ident changed to NDB Z Rwy 08

Revised coding will appear in Jeppesen NavData for cycle 1206, effective 31 May 2012. Until then an entry will appear in the NavData Change Notices beginning 11 May 12, and this Alert will be posted on the Jeppesen Web site (<http://ww1.jeppesen.com/company/alerts/aviation-alerts.jsp?region=LatinAmerica>).

WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:

Phone: 1-303-328-4445

E-mail: navdatatechsupport@jeppesen.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. They are distributed to affected ARINC 424 NavData users (avionics companies and other raw data users) and airlines receiving NavData directly from Jeppesen. Alerts are not distributed by Jeppesen to individual airline, business aviation or general aviation pilots, but are available to them on the Jeppesen Web site, www.jeppesen.com. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. Avionics users should consult with their database update service provider for definitive information on whether their system is affected by this Alert.