



JEPPesen®

NavData® Alert

!! URGENT !!

Date: 22 December 2008

Subject: Colombia (Multiple Locations)
Approach Procedures, SIDs and STARs
Cycle 0813

Incorrect SID and STAR Identifiers and Approach Information

Jeppesen NavData for 0813, effective 18 December 2008, contains incorrect data for multiple locations in Colombia. AIP Amendment 14/08 was received after the date specified by ICAO for aeronautical information distribution and after update cycle 0813 FMS/GPS navigation database had been processed and released. As a result, the changes contained therein could not be processed for the 18 December effective date. The changes include updates to Approach procedural information and SID and STAR identifiers.

Approach and STAR changes:

SKSM (Santa Marta): VOR Rwy 01 Approach [S01] and SEVIL1 STAR – Multiple changes.

DO NOT USE IN THE 0813 NAVDATA.

SKPE (Pereira): VOR Rwy 08 [S08] – Missed approach holding inbound course should be 203°. Vertical angle should be 3.00°.

EXERCISE CAUTION WHEN USING IN THE 0813 NAVDATA.

SKGO (Cartago): VOR Rwy 19 [S19] – Ending missed approach segment and holding is now based on the AXM VOR/DME instead of the AXM NDB.

DO NOT USE THE MISSED APPROACH PORTION OF THE PROCEDURE IN THE 0813 NAVDATA.

A full list of the SID and STAR identifiers changes are contained on the following page.

EXERCISE CAUTION WHEN USING THE SIDS AND STARS LISTED ON THE FOLLOWING PAGE OF THIS ALERT IN 0813 NAVDATA.

Revised coding will appear in Jeppesen NavData for cycle 0901, effective 15 January 2009. Until then an entry will appear in the NavData Change Notices beginning 9 January 2009, and this Alert will be posted on the Jeppesen Web site (<http://www.jeppesen.com/company/alerts/alerts-region.jsp?®ion=South+America>). Revised charts will be issued with a revision date of 9 JAN 09.

WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:

Phone: 303-328-4445

E-mail: navdatatechsupport@jeppesen.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. They are distributed to affected ARINC 424 NavData users (avionics companies and other raw data users) and airlines receiving NavData directly from Jeppesen. Alerts are not distributed by Jeppesen to individual airline, business aviation or general aviation pilots, but are available to them on the Jeppesen Web site, www.jeppesen.com. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. Avionics users should consult with their database update service provider for definitive information on whether their system is affected by this Alert.

The following SID/STAR identifiers are affected by the changes in AIP Amendment 14/08:

Location	SID/STAR	Old Ident	New Ident(s)
Arauca, Colombia (SKUC)	SID	ALEJO1	ALEJ1A
Arauca, Colombia (SKUC)	SID	GARCI2	GARC1A
Arauca, Colombia (SKUC)	SID	PALMA2	ALEJ1B/GARC1B/SVA1B/POXI1B/TRIN1B
Arauca, Colombia (SKUC)	SID	TRINI1	TRIN1A
Cali, Colombia (SKCL)	STAR	ULQ1A	ULQ2A
Pereira, Colombia (SKPE)	SID	CARTA1	TORO1B
Pereira, Colombia (SKPE)	STAR	EPO1	EPO1C
Pereira, Colombia (SKPE)	SID	MATEC1	LNA1/MATR1B/SEDI1B
Pereira, Colombia (SKPE)	SID	PERLA1	AXM1B/EPO1C/ZARZ1B
Pereira, Colombia (SKPE)	STAR	TOROL1	TORO1A

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:

Phone: 303-328-4445

E-mail: navdatatechsupport@jeppesen.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. They are distributed to affected ARINC 424 NavData users (avionics companies and other raw data users) and airlines receiving NavData directly from Jeppesen. Alerts are not distributed by Jeppesen to individual airline, business aviation or general aviation pilots, but are available to them on the Jeppesen Web site, www.jeppesen.com. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. Avionics users should consult with their database update service provider for definitive information on whether their system is affected by this Alert.