



**JEPPESEN<sup>®</sup>**  
**NavData<sup>®</sup> Alert**

**!! URGENT !!**

**Date:** 28 September 2011

**Subject:** Rotterdam, Netherlands  
Rotterdam (EHRD)  
ILS DME Rwy 24 [I24]  
VOR DME Rwy 24 [D24]  
Cycle 1110

***Incorrect Approach Transition Coding***

Jeppesen NavData for cycle 1110, effective 22 Sept 2011, contains incorrect approach transition coding on the MASOS [MASOS] transition on the ILS DME Rwy 24 [I24] and the VOR DME Rwy 24 [D24] approach procedures at Rotterdam, Netherlands (EHRD).

**THEREFORE, DO NOT USE THE MASOS [MASOS] TRANSITION ON THE ILS DME RWY 24 [I24] OR VOR DME RWY 24 [D24] APPROACH PROCEDURE IN CYCLE 1110 NAVDATA.**

Revised coding will appear in Jeppesen NavData for cycle 1111, effective 20 Oct 2011. Until then, an entry will appear in the NavData Change Notices beginning 07 Oct 11, and this Alert will be posted on the Jeppesen Web site:

(<http://ww1.jeppesen.com/main/corporate/company/alerts/aviation-alerts.jsp?region=EuropeMediterranean>).

Please refer to the Rotterdam, Netherlands (EHRD) 11-2 and 13-2 charts dated 22 Jul 11 (effective 28 Jul 11) for valid information.

**WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!**

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:

Phone: 1-303-328-4445

E-mail: [navdatatechsupport@jeppesen.com](mailto:navdatatechsupport@jeppesen.com)

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. They are distributed to affected ARINC 424 NavData users (avionics companies and other raw data users) and airlines receiving NavData directly from Jeppesen. Alerts are not distributed by Jeppesen to individual airline, business aviation or general aviation pilots, but are available to them on the Jeppesen Web site, [www.jeppesen.com](http://www.jeppesen.com). Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. Avionics users should consult with their database update service provider for definitive information on whether their system is affected by this Alert.