



JEPPESEN[®]
NavData[®] Alert

!! URGENT !!

Date: 18 June 2012

Subject: Warsaw, Poland
Chopin (EPWA)
RNAV SID XIMBA 2G [XIMB2G]
Cycle 1207

Incorrect Procedure Identifier

Jeppesen NavData for cycle 1207, effective 28 Jun 2012, contains an incorrect RNAV Standard Instrument Departure Procedure (SID) Identifier for Chopin Airport; Warsaw, Poland (EPWA). The XIMBA 2G [XIMB2G] RNAV Standard Instrument Departure Procedure has been up numbered to XIMBA 3G [XIMB3G].

THEREFORE, EXERCISE CAUTION WHEN SELECTING RNAV STANDARD INSTRUMENT DEPARTURE PROCEDURES FOR CHOPIN AIRPORT (EPWA) IN CYCLE 1207 NAVDATA.

Revised coding will appear in Jeppesen NavData for cycle 1208, effective 26 July 2012. Until then an entry will appear in the NavData Change Notices beginning 22 Jun 2012, and this Alert will be posted on the Jeppesen Web site

(<http://ww1.jeppesen.com/company/alerts/aviation-alerts.jsp?region=Eastern%20Europe>)

WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:

Phone: 303-328-4445

E-mail: navdatatechsupport@jeppesen.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. They are distributed to affected ARINC 424 NavData users (avionics companies and other raw data users) and airlines receiving NavData directly from Jeppesen. Alerts are not distributed by Jeppesen to individual airline, business aviation or general aviation pilots, but are available to them on the Jeppesen Web site, www.jeppesen.com. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. Avionics users should consult with their database update service provider for definitive information on whether their system is affected by this Alert.

EPWA 1207