



JEPPESEN.

NavData® Alert

!! URGENT !!

Date: 27 September 2012

Subject: Barranquilla, Colombia
Ernesto Cortissoz (SKBQ)
ILS Y Rwy 05 [I05-Y]
ILS Z Rwy 05 [I05-Z]
VOR Rwy 05 [D05 or S05]
Cycle 1210

Approach Procedures suspended

Jeppesen NavData for cycle 1210, effective 20 September 2012, contains suspended approaches at Ernesto Cortissoz; Barranquilla, Colombia (SKBQ). Colombia AIP Supplement A25/12 suspended all existing approaches into Rwy 05 Until 04 December 2012. Colombia AIP Supplement A25/12 also established Temporary procedures LOC Rwy 05 and VOR Rwy 05 for use until 04 December 2012.

THEREFORE DO NOT USE THE FOLLOWING APPROACH PROCEDURES IN NAVDATA CYCLE 1210.

Procedure Ident
ILS Y Rwy 05 [I05-Y]
ILS Z Rwy 05 [I05-Z]
VOR Rwy 05 [D05 or S05]

The Temporary procedures will appear in Jeppesen NavData for cycle 1211, effective 18 October 2012. Until then an entry will appear in the NavData Change Notices beginning 05 OCT 12, and this Alert will be posted on the Jeppesen Web site (<http://www1.jeppesen.com/company/alerts/aviation-alerts.region=SouthAmerica>).

WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:

Phone: 1-303-328-4445

E-mail: navdatatechsupport@jeppesen.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. They are distributed to affected ARINC 424 NavData users (avionics companies and other raw data users) and airlines receiving NavData directly from Jeppesen. Alerts are not distributed by Jeppesen to individual airline, business aviation or general aviation pilots, but are available to them on the Jeppesen Web site, www.jeppesen.com. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. Avionics users should consult with their database update service provider for definitive information on whether their system is affected by this Alert.

SKBQ 1210

APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:

Phone: 1-303-328-4445

E-mail: navdatatechsupport@jeppesen.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. They are distributed to affected ARINC 424 NavData users (avionics companies and other raw data users) and airlines receiving NavData directly from Jeppesen. Alerts are not distributed by Jeppesen to individual airline, business aviation or general aviation pilots, but are available to them on the Jeppesen Web site, www.jeppesen.com. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. Avionics users should consult with their database update service provider for definitive information on whether their system is affected by this Alert.