



JEPPESEN.
NavData® Alert

!! URGENT !!

Date: 27 April 2012

Subject: Bend, Oregon
Bend Mun (KBDN)
RNAV (GPS) Rwy 34 [R34]
Cycles 1204 1205

Incorrect Missed Approach Hold Turn Direction

Jeppesen NavData for cycles 1204 and 1205, effective 5 April 2012 and 3 May 2012 respectively, contain an incorrect missed approach hold turn direction on the RNAV (GPS) Rwy 34 [R34] at Bend Mun; Bend, Oregon (KBDN).

THEREFORE, DO NOT USE THE MISSED APPROACH HOLD FOR THE RNAV (GPS) RWY 34 [R34] IN CYCLES 1204 AND 1205 NAVDATA.

Revised coding will appear in Jeppesen NavData for cycle 1206, effective 31 May 2012. Until then an entry will appear in the NavData Change Notices beginning 11 May 12 and this Alert will be posted on the Jeppesen Web site (<http://www.jeppesen.com/company/alerts/aviation-alerts.jsp?region=United States>).

WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:

Phone: 1-303-328-4445

E-mail: navdatatechsupport@jeppesen.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. They are distributed to affected ARINC 424 NavData users (avionics companies and other raw data users) and airlines receiving NavData directly from Jeppesen. Alerts are not distributed by Jeppesen to individual airline, business aviation or general aviation pilots, but are available to them on the Jeppesen Web site, www.jeppesen.com. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. Avionics users should consult with their database update service provider for definitive information on whether their system is affected by this Alert.

KGCN 1204 & 1205