



JEPPESEN[®]
NavData[®] Alert

!! URGENT !!

Date: 04 October 2011

Subject: Tuzla, Bosnia- Herzegovina
Tuzla Airport (LQTZ)
ILS Z Rwy 09 [I09-Z]
ILS W Rwy 09 [I09-W]
Cycle 1110

Incorrect Altitude at Tuzla NDB

Jeppesen NavData for cycle 1110, effective 22 September 2011, contains an incorrect altitude at Tuzla NDB [TU]. The Tuzla NDB [TU] is part of the OBISA [OBISA] Approach Transition, Tuzla NDB [TU] Approach Transitions and Final Approach on the ILS Z Rwy 09 [I09-Z] and ILS W Rwy 09 [I09-W] approach procedures at Tuzla Airport; Tuzla, Bosnia-Herzegovina (LQTZ). On the Final Approach, the correct altitude at the Final Approach Course Fix Tuzla NDB [TU] is 2900'. On the OBISA [OBISA] and Tuzla NDB [TU] Approach Transitions the correct altitude at Tuzla NDB [TU] is "at or above 2900' ".

THEREFORE, USE CAUTION WHEN USING THE ILS Z RWY 09 [I09-Z] AND ILS W RWY 09 [I09-W] APPROACH PROCEDURES IN CYCLE 1110 NAVDATA.

Revised coding will appear in Jeppesen NavData for cycle 1111, effective 20 October 2011. Until then an entry will appear in the NavData Change Notices beginning 14 OCT 11, and this Alert will be posted on the Jeppesen Web site

<http://www.jeppesen.com/main/corporate/company/alerts/aviation-alerts.jsp?region=Western%20Europe%20%26%20Mediterranean>

Jeppesen charts are also affected and a Chart Alert will be published on this Jeppesen Web site.

WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:
Phone: 303-328-4445

E-mail: navdatatechsupport@jeppesen.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. They are distributed to affected ARINC 424 NavData users (avionics companies and other raw data users) and airlines receiving NavData directly from Jeppesen. Alerts are not distributed by Jeppesen to individual airline, business aviation or general aviation pilots, but are available to them on the Jeppesen Web site, www.jeppesen.com. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. Avionics users should consult with their database update service provider for definitive information on whether their system is affected by this Alert.

LQTZ CYCLE 1110