



## **!! URGENT !!**

**Date:** 24 September 2008

**Subject:** Brasilia, Brazil  
Pres Juscelino Kubitschek Intl (SBBR)  
VOR Rwy 11R [V11R]  
Cycle 0810

### ***Approach Transition [XMA] Unusable***

Jeppesen NavData for cycle 0810, effective 25 September 2008, contains incorrect data on the [XMA] approach transition on the VOR Rwy 11R [V11R] approach at Brasilia, Brazil (SBBR).

**THEREFORE, DO NOT USE THE APPROACH TRANSITION [XMA] FOR THE VOR RWY 11R [V11R] APPROACH PROCEDURE AT PRES JUSCELINO KUBITSCHKEK INTL (SBBR) IN CYCLE 0810 NAVDATA.**

Revised coding will appear in Jeppesen NavData for cycle 0811, effective 23 October 2008. Until then an entry will appear in the NavData Change Notices beginning 10 October 08, and this Alert will be posted on the Jeppesen Web site ([www.jeppesen.com](http://www.jeppesen.com), click on Aviation Resources, On-line Publications, NavData NOTAMs/Alerts). Corrected chart will be available in the 17 October 2008 revision.

**WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!**

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:

Phone: 303-328-4445 Fax: 303-328-4122

E-mail: [navdatatechsupport@jeppesen.com](mailto:navdatatechsupport@jeppesen.com)

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. They are distributed to affected ARINC 424 NavData users (avionics companies and other raw data users) and airlines receiving NavData directly from Jeppesen. Alerts are not distributed by Jeppesen to individual airline, business aviation or general aviation pilots, but are available to them on the Jeppesen Web site, [www.jeppesen.com](http://www.jeppesen.com). Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. Avionics users should consult with their database update service provider for definitive information on whether their system is affected by this Alert.

SBBR 0810