



JEPPesen®

NavData® Alert

!! URGENT !!

Date: 5 January 2009

Subject: Nanning, PR of China
Wuxu (ZGNN)
Multiple SID, STAR and Approach Procedures
Cycle 0901

Terminal Procedures/Transitions Unusable

Jeppesen NavData for cycle 0901, effective 15 January 2009, contains incorrect Standard Instrument Departure (SID), Standard Instrument Arrival (STAR) and Terminal Approach Procedure Transition Information for Wuxu Airport, Nanning, PR of China (ZGNN). AIP China Supplement Nr. 02/09 was received after the date specified by ICAO for aeronautical information distribution. As a result, the changes contained therein could not be processed for the 15 January effective date. The changes include multiple updates to SIDs and STARs and Approach Procedures.

THEREFORE, FOR NAVDATA CYCLE 0901, DO NOT USE THE SID, STAR AND TERMINAL APPROACH PROCEDURE TRANSITIONS LISTED BELOW.

Standard Instrument Arrival Procedures (STARs)
All STARs
Standard Instrument Departures (SIDs)
BHY 01D [BHY01D]
BHY 11D [BHY11D]
Approach Procedures (Only Transitions Affected)
ILS Rwy 05 [I05] – Transition [A] and Transition [B].
VOR DME Rwy 05 [D05] - Transition [A] and Transition [B].
VOR DME Rwy 23 [D23] - Transition [C] and Transition [D].

Revised coding will appear in Jeppesen Navdata for cycle 0902, effective 12 February 2009. Until then an entry will appear in the NavData Change Notices beginning with the 09 JAN 09 revision (additional NavData Change Notice updates to reflect the changes in AIP China Supp Nr. 02/09 are planned for the 16 JAN 09 revision), and this Alert will be posted on the Jeppesen Web site (www.jeppesen.com/company/alerts/alerts.jsp). Jeppesen charts for Nanning, PR of China, Wuxu (ZGNN) will be updated to reflect the correct information in the 09 January 09 revision.

**WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO
APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!**

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:

Phone: 303-328-4445 Fax: 303-328-4122

E-mail: navdatatechsupport@jeppesen.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. They are distributed to affected ARINC 424 NavData users (avionics companies and other raw data users) and airlines receiving NavData directly from Jeppesen. Alerts are not distributed by Jeppesen to individual airline, business aviation or general aviation pilots, but are available to them on the Jeppesen Web site, www.jeppesen.com. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. Avionics users should consult with their database update service provider for definitive information on whether their system is affected by this Alert.

0901 ZGNN