



JEPPESEN®

NavData® Alert

!! URGENT !!

Date: 12 April 2013

Subject: Chengdu, PR of China
Shuangliu (ZUUU)
CZH-01D [CZH01D] Departure Runway 02L
Cycle 1304

Incorrect coding on Departure

Jeppesen NavData for cycle 1304, effective 4 APR, contains an incorrect coding on the CZH-01D [CZH01D] Departure Runway 02L at Chengdu / Shuangliu, PR of China (ZUUU):

Incorrect coding sequence	Correct coding sequence
[D024G] - [D245M] - CTU - CZH	[D024G] - [D245M] - Z - CZH

THEREFORE, EXERCISE CAUTION WHEN USING CZH-01D [CZH01D] DEPARTURE IN CYCLE 1304 NAVDATA.

Correct coding will appear in Jeppesen NavData for cycle 1305, effective 02 MAY 2013. Until then, an entry will appear in the NavData Change Notices, and this Alert will be posted on the Jeppesen Web site (<http://www1.jeppesen.com/company/alerts/aviation-alerts.jsp?region=China>).

For correct information, refer to Chengdu / Shuangliu, PR of China (ZUUU) chart (10-3), dated 22 MAR 13, Eff 4 APR.

WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:

Phone: 303-328-4445

E-mail: navdatatechsupport@jeppesen.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. They are distributed to affected ARINC 424 NavData users (avionics companies and other raw data users) and airlines receiving NavData directly from Jeppesen. Alerts are not distributed by Jeppesen to individual airline, business aviation or general aviation pilots, but are available to them on the Jeppesen Web site, www.jeppesen.com. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. Avionics users should consult with their database update service provider for definitive information on whether their system is affected by this Alert.

ZUUU 1304