



JEPPESEN.
NavData® Alert

!! URGENT !!

Date: 03 May 2012

Subject: Warner Robins, Georgia
Robins AFB (KWRB)
RNAV (GPS) Rwy 15 [R15]
Cycle 1205

Incorrect Missed Approach Hold

Jeppesen NavData for cycle 1205 effective 03 May 2012 contains an incorrect missed approach hold at LETIC on RNAV (GPS) Rwy 15 [R15] Robins AFB; Warner Robins, GA (KWRB). The correct inbound holding bearing at LETIC should be 326 degrees.

THEREFORE, DO NOT USE RNAV (GPS) RWY 15 [R15] MISSED APPROACH HOLD IN CYCLE 1205 NAVDATA.

Revised coding will appear in Jeppesen NavData for cycle 1206, effective 31 May 2012. Until then an entry will appear in the NavData Change Notices beginning 11 May 2012, and this Alert will be posted on the Jeppesen Web site (<http://www.jeppesen.com/company/alerts/aviation-alerts>).

WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:
Phone: 303-328-4445
E-mail: navdatatechsupport@jeppesen.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. They are distributed to affected ARINC 424 NavData users (avionics companies and other raw data users) and airlines receiving NavData directly from Jeppesen. Alerts are not distributed by Jeppesen to individual airline, business aviation or general aviation pilots, but are available to them on the Jeppesen Web site, www.jeppesen.com. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. Avionics users should consult with their database update service provider for definitive information on whether their system is affected by this Alert.

KWRB 1205