



JEPPESSEN.

NavData® Alert

!! URGENT !!

Date: 1 June 2012

Subject: Lima-Callao, Peru
Jorge Chavez Intl (SPIM) and vicinity
Departure/Arrival and Airways

Multiple Changes to NavData

Jeppesen NavData for cycle 1206, effective 31 May 2012, contains incorrect data. This data was updated in cycle 1206 (Eff 31 May 2012) per Peru AIP Supplements 20-21/12 and 16-19/12. Peru NOTAMs A2049 and A2050 were issued and postponed the changes in the Peru AIP Supplements until 28 Jun 2012.

Therefore do NOT use the following in the table below.

Procedure Ident	Procedure Name	Transition
LIM4	Lima 4 Departure	ILPIP
ILPIP1	ILPIP ONE Departure	
ILPIP1	STAR ILPIP 1	
Airway Designator	From	To
T218	Lima (LIM) VOR	Puerto Maldonado (PDO) VOR
UT218	Lima (LIM) VOR	BODET
T226	ASEMO CRP	KADEL CRP
UT226	ASEMO CRP	KADEL CRP

THEREFORE, DO NOT USE THE ABOVE MENTIONED IN CYCLE 1206 NAVDATA.

Revised coding will appear in Jeppesen NavData for cycle 1207, effective 28 Jun 2012. Until then an entry will appear in the NavData Change Notices beginning 15 June 2012, and this Alert will be posted on the Jeppesen Web site (<http://www.jeppesen.com/company/alerts/aviation-alerts>).

**WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO
APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!**

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:

Phone: 303-328-4445

E-mail: navdatatechsupport@jeppesen.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. They are distributed to affected ARINC 424 NavData users (avionics companies and other raw data users) and airlines receiving NavData directly from Jeppesen. Alerts are not distributed by Jeppesen to individual airline, business aviation or general aviation pilots, but are available to them on the Jeppesen Web site, www.jeppesen.com. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. Avionics users should consult with their database update service provider for definitive information on whether their system is affected by this Alert.