



JEPPesen®

NavData® Alert

!! URGENT !!

Date: 06 June 2012

Subject: Boscombe Down, United Kingdom
Boscombe Down (EGDM)
TACAN Rwy 23 [T23]
Cycle 1206

Incorrect Approach Transition Information - Altitude

Jeppesen NavData for cycle 1206, effective 31 May 2012, contains incorrect altitude information within the D2700 ONE [D2701] and D2700 TWO [D2702] Approach Transitions of the TACAN Rwy 23 [T23] approach procedure at Boscombe Down Airport; Boscombe Down, United Kingdom (EGDM). The correct altitude at the Boscombe Down TACAN [BDN] should read "At or above FL050". The correct altitude at DME 10.0 BDN on the outbound leg should read "At or above 3390'".

THEREFORE, EXERCISE CAUTION WHEN SELECTING THE D2700 ONE [D2701] AND D2700 TWO [D2702] APPROACH TRANSITIONS FOR THE TACAN RWY 23 [T23] APPROACH PROCEDURE IN CYCLE 1206 NAVDATA.

Revised coding will appear in Jeppesen NavData for cycle 1207, effective 28 June 2012. Until then an entry will appear in the NavData Change Notices beginning 22 Jun 2012, and this Alert will be posted on the Jeppesen Web site

<http://www1.jeppesen.com/company/alerts/aviation-alerts.jsp?region=Western%20Europe%20%26%20Mediterranean>

WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:

Phone: 303-328-4445

E-mail: navdatatechsupport@jeppesen.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. They are distributed to affected ARINC 424 NavData users (avionics companies and other raw data users) and airlines receiving NavData directly from Jeppesen. Alerts are not distributed by Jeppesen to individual airline, business aviation or general aviation pilots, but are available to them on the Jeppesen Web site, www.jeppesen.com. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. Avionics users should consult with their database update service provider for definitive information on whether their system is affected by this Alert.

EGDM 1206