



JEPPESEN®

NavData® Alert

!! URGENT !!

Date: 20 Oct 2012

Subject: Brize Norton, United Kingdom
Brize Norton (EGVN)
Departure and Approach procedures
Cycle 1211

Incorrect Departure and Approach procedures due to late incoming source

UNITED KINGDOM MIL AIRAC AMDT 11/12, effective 18 OCT 12 was received after the date specified by ICAO for aeronautical information distribution. As a result, Jeppesen NavData for cycle 1211, effective 18 October 2012, contains incorrect Departure and Approach procedures at Brize Norton, United Kingdom (EGVN).

Approach Procedure	Instruction
ILS DME Rwy 08 [I08]	DO NOT USE
LCTR DME Rwy 08 [Q08]	DO NOT USE
TACAN Rwy 08 [T08]	DO NOT USE
ILS DME Rwy 26 [I26]	DO NOT USE
LCTR DME Rwy 26 [Q26]	DO NOT USE
TACAN Rwy 26 [T26]	DO NOT USE

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:

Phone: 303-328-4445

E-mail: navdatatechsupport@jeppesen.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. They are distributed to affected ARINC 424 NavData users (avionics companies and other raw data users) and airlines receiving NavData directly from Jeppesen. Alerts are not distributed by Jeppesen to individual airline, business aviation or general aviation pilots, but are available to them on the Jeppesen Web site, www.jeppesen.com. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. Avionics users should consult with their database update service provider for definitive information on whether their system is affected by this Alert.

Departure Procedure	Instruction
MALBY	DO NOT USE
OSGOD	DO NOT USE
ALPHA (Rwy 08)	After climbing on rwy track to 1800', cross D9.0 Brize Norton (BZN) TACAN at 1800'
ALPHA (Rwy 26)	After climbing on rwy track to 1800', cross D8.0 Brize Norton (BZN) TACAN at 1800'
BRAVO (Rwy 08)	After climbing on rwy track to 2800', cross D9.0 Brize Norton (BZN) TACAN at 2800'
BRAVO (Rwy 26)	After climbing on rwy track to 2800', cross D8.0 Brize Norton (BZN) TACAN at 2800'

Revised coding will appear in Jeppesen NavData for cycle 1212, effective 15 November 2012. Until then an entry will appear in the NavData Change Notices and this Alert will be posted on the Jeppesen Web site: <http://www1.jeppesen.com/company/alerts/aviation-alerts.jsp?region=Western%20Europe%20%26%20Mediterranean>

WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:

Phone: 303-328-4445

E-mail: navdatatechsupport@jeppesen.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. They are distributed to affected ARINC 424 NavData users (avionics companies and other raw data users) and airlines receiving NavData directly from Jeppesen. Alerts are not distributed by Jeppesen to individual airline, business aviation or general aviation pilots, but are available to them on the Jeppesen Web site, www.jeppesen.com. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. Avionics users should consult with their database update service provider for definitive information on whether their system is affected by this Alert.