



JEPPESEN.
NavData® Alert

!! URGENT !!

Date: 11 January 2012

Subject: Colombia
Multiple Airports
Arrival, Departure and Approach procedures
Cycle 1201

Numerous Changes Effective 12 JAN 2012

Jeppesen NavData for cycle 1201, effective 12 January 2012, contains out of date information. Several Colombian AIP Supplements were received after the date specified by ICAO for aeronautical information distribution. As a result, changes to the Approaches, Arrivals, and Departures listed below could not be processed for the 12 JAN 2012 effective date.

THEREFORE, DO NOT USE THE SID/STAR/APPROACH PROCEDURES LISTED ON THE FOLLOWING PAGE IN CYCLE 1201 NAVDATA.

Revised coding will appear in Jeppesen NavData for cycle 1202, effective 09 February 2012. Until then an entry will appear in the NavData Change Notices beginning 20 JAN 12, and this Alert will be posted on the Jeppesen Web site (<http://ww1.jeppesen.com/company/alerts/aviation-alerts.jsp?region=South%20America>).

WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:

Phone: 1-303-328-4445

E-mail: navdatatechsupport@jeppesen.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. They are distributed to affected ARINC 424 NavData users (avionics companies and other raw data users) and airlines receiving NavData directly from Jeppesen. Alerts are not distributed by Jeppesen to individual airline, business aviation or general aviation pilots, but are available to them on the Jeppesen Web site, www.jeppesen.com. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. Avionics users should consult with their database update service provider for definitive information on whether their system is affected by this Alert.

DO NOT USE THE FOLLOWING PROCEDURES

Florencia, Colombia – Gustavo A Paredes Airport (SKFL)

Procedure	IDENT
NEMAL TWO ALFA ARRIVAL	NEMA2A
FLORENCIA ONE BRAVO DEPARTURE	FLA1B
FLORENCIA TWO CHARLIE DEPARTURE	FLA2C
VOR CIRCLING Rwy 12/30	VOR

Neiva, Colombia – Benito Salas Airport (SKNV)

Procedure	IDENT
ISABE TWO ALFA ARRIVAL	ISAB2A
PANER ONE ALFA ARRIVAL	PANE1A
PUMUS TWO ARRIVAL	PUMUS2
USANA TWO ARRIVAL	USANA2
NEIVA ONE ALFA DEPARTURE	NVA1A
NEIVA TWO BRAVO DEPARTURE	NVA2B
PUMUS ONE ALFA DEPARTURE	PUMU1A
PUMUS TWO BRAVO DEPARTURE	PUMU2B
SANTA ONE ALFA DEPARTURE	SANT1A
SANTA TWO BRAVO DEPARTURE	SANT2B
VOR Rwy 02	D02
VOR Y Rwy 20	D20-Y

Puerto Asis, Colombia – Tres De Mayo Airport (SKAS)

Procedure	IDENT
ARAZA ONE DEPARTURE	ARAZA1
FLORENCIA ONE ALFA DEPARTURE	FLA1A
NDB Rwy 19	N19

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:

Phone: 1-303-328-4445

E-mail: navdatatechsupport@jeppesen.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. They are distributed to affected ARINC 424 NavData users (avionics companies and other raw data users) and airlines receiving NavData directly from Jeppesen. Alerts are not distributed by Jeppesen to individual airline, business aviation or general aviation pilots, but are available to them on the Jeppesen Web site, www.jeppesen.com. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. Avionics users should consult with their database update service provider for definitive information on whether their system is affected by this Alert.