



GARMIN®

Navigation Data Alert

TO: Users of all Garmin aviation products using a US VFR Navigation database
DATE: December 18, 2012
CYCLE: 1210-1211
SUBJECT: Incorrect runway identifiers at KWVI, Watsonville, CA

DESCRIPTION

The runway identifier of the east/west runway at KWVI was inaccurate in the 1210 and 1211 data cycles of the US VFR Navigation database.

Inaccurate database identifiers in 1210 and 1211 – **RWY 08/26**
Actual identifiers since 1210 – **RWY 09/27**

PILOT ACTION

Be aware of this identification error and understand that all database references to RWY 08/26 are for RWY 09/27.

RESOLUTION

These runway identifiers were updated by the FAA in the 1212 cycle of the US VFR Navigation database.

THIS ALERT SHOULD BE MADE AVAILABLE TO ALL USERS OF GARMIN AVIATION UNITS OR SYSTEMS UTILIZING THE US VFR NAVIGATION DATABASE BY AERONAV PRODUCTS

Garmin requests that the flight crew report any observed discrepancies related to database information. These discrepancies could come in the form of an incorrect procedure, incorrectly identified terrain, obstacles, fixes, or any other displayed item used for navigation or communication in the air or on the ground. Go to fly.garmin.com and select "[Aviation Data Error Report](#)."