



**!! URGENT !!**

**UPDATE**

**Date:** 14 November 2011

**Subject:** Nairobi, Kenya  
Jomo Kenyatta (HKJK)  
Multiple Arrival Procedures  
Cycle 1111 and 1112

***Procedure Identifiers (up-numbering) and changed Arrival Procedure Routing***

Jeppesen NavData for cycle 1111 and 1112, effective 20 October 2011 and 17 November 2011 respectively, does not contain the updated Standard Instrument Arrival Procedure (STAR) information for Jomo Kenyatta Airport, Nairobi, Kenya (HKJK) as published in AIP Amendment 4/11. AIP Amendment 4/11 was received late in October 2011. As a result, the changes contained therein could not be processed for the 28 July effective date and later Navdata cycles.

**THEREFORE, DO NOT USE THE STANDARD INSTRUMENT ARRIVAL PROCEDURES (STAR) AFFECTED BY ROUTING AND PROCEDURE IDENT CHANGES AS LISTED ON THE FOLLOWING PAGE IN CYCLE 1111 NAVDATA.**

**EXERCISE CAUTION IN CYCLE 1111 AND 1112 NAVDATA WHEN USING STANDARD INSTRUMENT ARRIVAL PROCEDURES AFFECTED BY PROCEDURE IDENTIFIER UPDATES ONLY (UP-NUMBERING) AS LISTED ON THE FOLLOWING PAGES.**

Revised coding will appear in Jeppesen NavData for cycle 1112, effective 17 November 2011, and cycle 1113, effective 15 December 2011 (**NAK 2P [NAK2P]**). Until then an entry will appear in the NavData Change Notices beginning 04 NOV 11, and this Alert will be posted on the Jeppesen Web site

<http://www.jeppesen.com/company/alerts/aviation-alerts.jsp?region=Africa>

**WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!**

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:  
Phone: 303-328-4445

E-mail: [navdatatechsupport@jeppesen.com](mailto:navdatatechsupport@jeppesen.com)

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. They are distributed to affected ARINC 424 NavData users (avionics companies and other raw data users) and airlines receiving NavData directly from Jeppesen. Alerts are not distributed by Jeppesen to individual airline, business aviation or general aviation pilots, but are available to them on the Jeppesen Web site, [www.jeppesen.com](http://www.jeppesen.com). Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. Avionics users should consult with their database update service provider for definitive information on whether their system is affected by this Alert.

HKJK CYCLE 1111\_1112

**Standard Instrument Arrival Procedures (STAR) affected by routing and procedure identifier changes. Do not use the following procedures in cycle 1111 NavData:**

Procedure Ident old	Procedure Ident new	Remark
AVITU 1P [AVIT1P]	AVITU 2P [AVIT2P]	Routing changed
KOBAB 1P [KOBA1P]	KOBAB 2P [KOBA2P]	Routing changed
KAPAL 1P [KAPA1P]	KAPAL 2P [KAPA2P]	Routing changed
PASUN 1P [PASU1P]	PASUN 2P [PASU2P]	Routing changed
IMSAN 1P [IMSA1P]	IMSAN 2P [IMSA2P]	Routing changed
IMSAN 1R [IMSA1R]	IMSAN 2R [IMSA2R]	Routing changed
GABSO 1P [GABS1P]	GABSO 2P [GABS2P]	Routing changed
GABSO 1R [GABS1R]	GABSO 2R [GABS2R]	Routing changed
UTATA 1P [UTAT1P]	UTATA 2P [UTAT2P]	Routing changed
UTATA 1R [UTAT1R]	UTATA 2R [UTAT2R]	Routing changed

**Standard Instrument Arrival Procedures (STAR) affected by Procedure Identifier Updates (up-numbering) only. Exercise caution when using the following procedures in cycle 1111 NavData:**

Procedure Ident old	Procedure Ident new	Remark
LOTAS 1P [LOTA1P]	LOTAS 2P [LOTA2P]	No routing changes
LADAN 1P [LADA1P]	LADAN 2P [LADA2P]	No routing changes
LADAN 1R [LADA1R]	LADAN 2R [LADA2R]	No routing changes
TILUK 1P [TILU1P]	TILUK 2P [TILU2P]	No routing changes
TILUK 1R [TILU1R]	TILUK 2R [TILU2R]	No routing changes
NAK 1P [NAK1P]	NAK 2P [NAK2P]	No routing changes
NAK 1R [NAK1R]	NAK 2R [NAK2R]	No routing changes
APMES 1P [APME1P]	APMES 2P [APME2P]	No routing changes
APMES 1R [APME1R]	APMES 2R [APME2R]	No routing changes
NAKAT 1P [NAKA1P]	NAKAT 2P [NAKA2P]	No routing changes
NAKAT 1R [NAKA1R]	NAKAT 2R [NAKA2R]	No routing changes

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:  
Phone: 303-328-4445

E-mail: [navdatatechsupport@jeppesen.com](mailto:navdatatechsupport@jeppesen.com)

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. They are distributed to affected ARINC 424 NavData users (avionics companies and other raw data users) and airlines receiving NavData directly from Jeppesen. Alerts are not distributed by Jeppesen to individual airline, business aviation or general aviation pilots, but are available to them on the Jeppesen Web site, [www.jeppesen.com](http://www.jeppesen.com). Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. Avionics users should consult with their database update service provider for definitive information on whether their system is affected by this Alert.

EKBAD 1P [EKBA1P]	EKBAD 2P [EKBA2P]	No routing changes
EKBAD 1R [EKBA1R]	EKBAD 2R [EKBA2R]	No routing changes
PARIN 1P [PARI1P]	PARIN 2P [PARI2P]	No routing changes
PARIN 1R [PARI1R]	PARIN 2R [PARI2R]	No routing changes
EVATO 1P [EVAT1P]	EVATO 2P [EVAT2P]	No routing changes
EVATO 1R [EVAT1R]	EVATO 2R [EVAT2R]	No routing changes
AVITU 1R [AVIT1R]	AVITU 2R [AVIT2R]	No routing changes
KOBAB 1R [KOBA1R]	KOBAB 2R [KOBA2R]	No routing changes
KAPAL 1R [KAPA1R]	KAPAL 2R [KAPA2R]	No routing changes
PASUN 1R [PASU1R]	PASUN 2R [PASU2R]	No routing changes

**Standard Instrument Arrival Procedures (STAR) affected by Procedure Identifier Updates (up-numbering) only. Exercise caution when using the following procedures in cycle 1112 NavData:**

Procedure Ident old	Procedure Ident new	Remark
NAK 1P [NAK1P]	NAK 2P [NAK2P]	No routing changes

**Standard Instrument Arrival Procedures (STAR) not contained in cycle 1111 Navdata:**

Procedure Ident
LOTAS 1R [LOTA1R]

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:

Phone: 303-328-4445

E-mail: [navdatatechsupport@jeppesen.com](mailto:navdatatechsupport@jeppesen.com)

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. They are distributed to affected ARINC 424 NavData users (avionics companies and other raw data users) and airlines receiving NavData directly from Jeppesen. Alerts are not distributed by Jeppesen to individual airline, business aviation or general aviation pilots, but are available to them on the Jeppesen Web site, [www.jeppesen.com](http://www.jeppesen.com). Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. Avionics users should consult with their database update service provider for definitive information on whether their system is affected by this Alert.