



JEPPESEN®

NavData® Alert

!! URGENT !!

Date: 07 Dec 2012

Subject: Kisumu, Kenya
Kisumu (HKKI)
Approach procedures
Cycle 1213

Incorrect and missing Approach procedures due to late incoming source

KENYA AIP SUPPLEMENT 15/12, effective 13 DEC 12 was received after the date specified by ICAO for aeronautical information distribution. As a result, Jeppesen NavData for cycle 1213, effective 13 December 2012, contains incorrect RNAV Approach procedures and is missing VORDME Approach procedures at Kisumu, Kenya (HKKI):

Approach Procedure	Instruction
RNAV (GNSS) Rwy 06 [R06]	DO NOT USE in NavData 1213
RNAV (GNSS) Rwy 24 [R24]	DO NOT USE in NavData 1213
VOR DME Rwy 06 [D06]	Not available in NavData 1213
VOR DME Rwy 24 [D24]	Not available in NavData 1213

Revised coding will appear in Jeppesen NavData for cycle 1301, effective 10 January 2013. Until then, an entry will appear in the NavData Change Notices and this Alert will be posted on the Jeppesen Web site: <http://www1.jeppesen.com/company/alerts/aviation-alerts.jsp?region=Africa>

Please refer also to updated charts dated **14 DEC 12**.

**WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO
APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!**

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:

Phone: 303-328-4445

E-mail: navdatatechsupport@jeppesen.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. They are distributed to affected ARINC 424 NavData users (avionics companies and other raw data users) and airlines receiving NavData directly from Jeppesen. Alerts are not distributed by Jeppesen to individual airline, business aviation or general aviation pilots, but are available to them on the Jeppesen Web site, www.jeppesen.com. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. Avionics users should consult with their database update service provider for definitive information on whether their system is affected by this Alert.

HKKI 1213