



JEPPESEN[®]

NavData[®] Alert

!! URGENT !!

Date: 07 Sep 2012

Subject: Madrid, Spain
Barajas (LEMD)
ILS W Rwy 32R (I32RW)
Cycle 1210

Incorrect ident and coding missing

Jeppesen NavData for cycle 1210, effective 20 Sep 2012, contains an incorrect approach procedure identifier. ILS X Rwy 32R [I32RX] procedure name and ident should read ILS W Rwy 32R [I32RW] at Barajas Airport; Madrid, Spain (LEMD).

ILS X Rwy 32R [I32RX] coding is missing from cycle 1210 NavData.

THEREFORE USE CAUTION WHEN CLEARED TO ILS W RWY 32R [I32RW] AT BARAJAS AIRPORT; MADRID, SPAIN (LEMD) IN CYCLE 1210.

Revised coding will appear in Jeppesen NavData for cycle 1211, effective 18 Oct 2012. Until then an entry will appear in the NavData Change Notices beginning 20 Sep 2012, and this Alert will be posted on the Jeppesen Web site (<http://www.jeppesen.com/company/alerts/aviation-alerts>).

WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:

Phone: 303-328-4445

E-mail: navdatatechsupport@jeppesen.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. They are distributed to affected ARINC 424 NavData users (avionics companies and other raw data users) and airlines receiving NavData directly from Jeppesen. Alerts are not distributed by Jeppesen to individual airline, business aviation or general aviation pilots, but are available to them on the Jeppesen Web site, www.jeppesen.com. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. Avionics users should consult with their database update service provider for definitive information on whether their system is affected by this Alert.

LEMD 1210