



JEPPESEN[®]

NavData[®] Alert

!! URGENT !!

Date: 22 June 2012

Subject: Palma De Mallorca, Spain
Palma De Mallorca (LEPA)
Continuous Descent Arrival Procedure GODOX 1DCP [GO1DCP]
Cycles 1206 and 1207

Incorrect Continuous Descent Arrival Procedure (CDA) Information

Jeppesen NavData for cycles 1206 and 1207, effective 31 May 2012 and 28 Jun 2012 respectively, contains incorrect coding for the GODOX 1DCP [GO1DCP] Continuous Descent Arrival Procedure at Palma De Mallorca Airport; Palma De Mallorca, Spain (LEPA).

THEREFORE, DO NOT USE THE GODOX 1DCP [GO1DCP] CONTINUOUS DESCENT ARRIVAL PROCEDURE IN CYCLES 1206 AND 1207 NAVDATA.

Revised coding will appear in Jeppesen NavData for cycle 1208, effective 26 Jul 2012. Until then an entry will appear in the NavData Change Notices beginning 06 Jul 2012, and this Alert will be posted on the Jeppesen Web site

(<http://www1.jeppesen.com/company/alerts/aviation-alerts.jsp?region=Western%20Europe%20%26%20Mediterranean>).

Please refer to the Palma De Mallorca Airport, Palma De Mallorca, Spain (LEPA) 10-2K chart dated 27 Apr 12 (effective 3 May) for valid information.

WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:

Phone: 303-328-4445

E-mail: navdatatechsupport@jeppesen.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. They are distributed to affected ARINC 424 NavData users (avionics companies and other raw data users) and airlines receiving NavData directly from Jeppesen. Alerts are not distributed by Jeppesen to individual airline, business aviation or general aviation pilots, but are available to them on the Jeppesen Web site, www.jeppesen.com. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. Avionics users should consult with their database update service provider for definitive information on whether their system is affected by this Alert.

LEPA 1206 1207