



JEPPESEN.

NavData® Alert

!! URGENT !!

Date: 28 November 2012

**Subject: Luang Phabang, Laos
 Luang Phabang Intl (VLLB)
 Arrivals for Rwys 05 & 23
 VOR DME Rwy 05[D05]
 VOR DME Rwy 23[D23]
 Cycles 1212 and 1213**

Procedures Unusable

Laos AIP Amendment 07/12 was received after the date specified by ICAO for aeronautical information distribution. As a result, changes to the NavData could not be processed for the 15 November 2012 effective date. Jeppesen NavData for cycle 1212 effective 15 Nov 2012, and cycle 1213 effective 13 December contain incorrect information at; Luang Phabang Intl; Luang Phabang, Laos (VLLB). The following Procedures contain incorrect information and are unusable.

All Arrivals for Rwys 05 and 23
VOR DME Rwy 05[D05]
VOR DME Rwy 23[D23]

THEREFORE, DO NOT USE THE ABOVE PROCEDURES IN CYCLES 1212 AND 1213 NAVDATA.

Revised coding will appear in Jeppesen NavData for cycle 1301, effective 10 Jan 2013. Until then an entry will appear in the NavData Change Notices beginning 07 Dec 2012, and this Alert will be posted on the Jeppesen Web site at (<http://www.jeppesen.com/company/alerts/aviation-alerts.jsp>).

**WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE
TO APPROPRIATE CREW MEMBERS IMMEDIATELY!**

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:

Phone: 303-328-4445

E-mail: navdatatechsupport@jeppesen.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. They are distributed to affected ARINC 424 NavData users (avionics companies and other raw data users) and airlines receiving NavData directly from Jeppesen. Alerts are not distributed by Jeppesen to individual airline, business aviation or general aviation pilots, but are available to them on the Jeppesen Web site, www.jeppesen.com. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. Avionics users should consult with their database update service provider for definitive information on whether their system is affected by this Alert.

VLLB 1212 1213