

**JEPPESEN**
NavData® Alert**!! URGENT !!**

Date: 10 April 2008

Subject: Salvador, Brazil
Dep. Luis Eduardo Magalhaes INTL (SBSV)
RNAV (GNSS) Rwy 28 [R28]
Cycle 0804

Incorrect Inbound Course for Missed Approach Holding

Jeppesen NavData for cycle 0804, effective 10 April 2008, contains an incorrect inbound holding course of 282° for the missed approach holding (HM leg) at SV366 waypoint on the RNAV (GNSS) Rwy 28 [R28] at Dep. Luis Eduardo Magalhaes INTL (SBSV); Salvador, Brazil. The correct inbound holding course is 102°.

THEREFORE, DO NOT USE THE MISSED APPROACH SEGMENT OF THE RNAV (GNSS) RWY 28 [R28] PROCEDURE IN THE CYCLE 0804 NAVDATA.

Revised coding will appear in Jeppesen NavData for cycle 0805, effective 8 May 2008. Until then an entry will appear in the NavData Change Notices beginning 4 April 2008, and this Alert will be posted on the Jeppesen Web site (www.jeppesen.com, click on Aviation Resources, On-line Publications, NavData NOTAMs/Alerts). Please refer to the Salvador, Brazil (SBSV) 12-2 chart dated 4 April 08, eff 10 Apr 08 for valid information.

WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:
Phone: 303-328-4445 Fax: 303-328-4122
E-mail: navdatatechsupport@jeppesen.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. They are distributed to affected ARINC 424 NavData users (avionics companies and other raw data users) and airlines receiving NavData directly from Jeppesen. Alerts are not distributed by Jeppesen to individual airline, business aviation or general aviation pilots, but are available to them on the Jeppesen Web site, www.jeppesen.com. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. Avionics users should consult with their database update service provider for definitive information on whether their system is affected by this Alert.