

GARMIN®
Navigation Data Alert

TO: Users of all Garmin aviation products using a US VFR Navigation database

DATE: 8 August 2012

CYCLE: 1208 & 1209

SUBJECT: Incorrect Navaid Coordinates

DESCRIPTION

The FAA has advised Garmin that the coordinates for the following navaid in the 1208 & 1209 cycles of the US VFR Navigation Database by AeroNav Products are in error:

Navaid	Correct coordinates	Coordinates published in error
SMA (St Mary's NDB)	N62° 03.563 W163° 16.913	N62° 03.501 W163° 17.497

The following airways have segments whose courses are also impacted by this coordinate error: J179, A6, B27, G6, G15, V459, V496 and B932. Another alert will be issued to further explain this airway impact.

PILOT ACTION

Do not use the erroneous SMA NDB coordinates from cycles 1208 and 1209 in any manner.

RESOLUTION

These navaid coordinates will be corrected in the 1210 cycle of the US VFR Navigation database.

THIS ALERT SHOULD BE MADE AVAILABLE TO ALL USERS OF GARMIN AVIATION UNITS OR SYSTEMS UTILIZING THE US VFR NAVIGATION DATABASE BY AERONAV PRODUCTS

Garmin requests that the flight crew report any observed discrepancies related to database information. These discrepancies could come in the form of an incorrect procedure, incorrectly identified terrain, obstacles, fixes, or any other displayed item used for navigation or communication in the air or on the ground. Go to fly.garmin.com and select "[Aviation Data Error Report](#)."