



JEPPESEN[®]

NavData[®] Alert

!! URGENT !!

Date: 3 August 2012

Subject: Hoquiam, Washington
Bowerman (KHQM)
RNAV (GPS) Rwy 24 [R24]
Cycle 1208

Incorrect Path Point Information

Jeppesen NavData for cycle 1208, effective 26 July 2012, contains incorrect information within the Path Point (PP) record for the RNAV (GPS) Rwy 24 at Bowerman; Hoquiam, Washington (KHQM). The incorrect information provided in the Path Point record may directly impact the accuracy of the aircraft's path during operations.

THEREFORE, DO NOT USE THE RNAV (GPS) RWY 24 [R24] IN CYCLE 1208 NAVDATA.

Revised coding will appear in Jeppesen NavData for cycle 1209, effective 23 August 2012. Until then an entry will appear in the NavData Change Notices beginning 10 AUG 12, and this Alert will be posted on the Jeppesen Web site (<http://www1.jeppesen.com/company/alerts/aviation-alerts.region=UnitedStates>).

**WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO
APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!**

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:

Phone: 1-303-328-4445

E-mail: navdatatechsupport@jeppesen.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. They are distributed to affected ARINC 424 NavData users (avionics companies and other raw data users) and airlines receiving NavData directly from Jeppesen. Alerts are not distributed by Jeppesen to individual airline, business aviation or general aviation pilots, but are available to them on the Jeppesen Web site, www.jeppesen.com. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. Avionics users should consult with their database update service provider for definitive information on whether their system is affected by this Alert.

KHQM 1208