



## AVIATION SERVICE DOCUMENT NOTIFICATION

**TO:** Registered GTX 23 and GTX 330/330D w/ES Owners/Operators

**DATE:** 4 January 2013

**SUBJECT:** Software Version 7.02 available for GTX 23 and GTX 330/330D w/ES products (not applicable to GNS 480, G900X, G950, G1000, Cirrus Perspective®, or Embraer Prodigy™ installations)

### COMPLIANCE

**Optional:** Software Service Bulletin 1240 may be incorporated at the customer's request.

### PURPOSE

Software Version 7.02 for GTX 23 and GTX 330/330D w/ES products (not applicable to GNS 480, G900X, G950, G1000, Cirrus Perspective®, or Embraer Prodigy™ installations) updates Automatic Dependent Surveillance – Broadcast (ADS-B) function to TSO-C166b.

### PRODUCT AFFECTED

All GTX 23 units and all GTX 330/330D w/ES (Extended Squitter) units listed in Table 1 with Software Version 6.20 or previous software versions that are not installed with GNS 480, G900X, G950, G1000, Cirrus Perspective®, or Embraer Prodigy™ systems.

<b>NOTE</b>
-------------

This software service bulletin does not apply to non-ES enabled GTX 330/330D units.

The unit's current software version is displayed at power up on the GTX 330/330D front panel.

**Table 1**

Item	Unit Part Number
GTX 23	011-02803-02
GTX 330 w/ES, Black, Non-Diversity	011-00455-60
GTX 330 w/ES, Gray, Non-Diversity	011-00455-80
GTX 330D w/ES, Black, Diversity	011-00455-70
GTX 330D w/ES, Gray, Diversity	011-00455-90

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.