



AVIATION SERVICE DOCUMENT NOTIFICATION

TO: Registered Garmin GTN Owner/Operators
DATE: March 20, 2013
SUBJECT: This communication is intended to inform Garmin aviation customers of forthcoming service document Service Bulletin 1311: GTN 635/650 and GTN 750 Notification of Mod Level 2

COMPLIANCE

Recommended for installations that need the GTN to be qualified to RTCA/DO-160F, Section 8, Category U, Curve G vibration (typically used for helicopters).

Optional for all other installations.

PURPOSE

Mod Level 2 improves Com and Nav isolation for installations with limited room to space antennas, reducing the likelihood of GTN Com transmissions causing the squelch to break or the VOR receiver to flag.

The Mod Level 2 configuration is necessary for GTN Navigation System installations that need the GTN 750 to be qualified to RTCA/DO-160F, Section 8, Category U, Curve G vibration (typically used for helicopters).

PRODUCTS AFFECTED

GTN 635/650 and GTN 750

DESCRIPTION

This service bulletin provides instructions related to the disposition of the GTN 635/650 and GTN 750 as related to Mod Level 2.

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.