



AVIATION SERVICE DOCUMENT NOTIFICATION

TO: Registered Garmin GTN Owner/Operators
DATE: March 20, 2013
SUBJECT: This communication is intended to inform Garmin aviation customers of forthcoming service document Service Bulletin 1313: GTN 625/635/650 and GTN 725/750 Notification of Mod Level 3

COMPLIANCE

Recommended for installations that need the GTN to be qualified to RTCA/DO-160F, Section 8, Category U, Curve G vibration (typically used for helicopters).

Optional for all other installations

PURPOSE

Mod Level 3 configuration is necessary for GTN 625/635/650 and GTN 725/750 installations that need the GTN to be qualified to RTCA/DO-160F, Section 8, Category U, Curve G vibration (typically used for helicopters).

PRODUCTS AFFECTED

GTN 625/635/650 and GTN 725/750

DESCRIPTION

This service bulletin provides instructions related to the disposition of the GTN 625/635/650 and GTN 725/750 as related to Mod Level 3.

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.