



JEPPESEN®

NavData® Alert

!! URGENT !!

Date: 14 Sep 2012

Subject: Bordeaux, France
Merignac (LFBD)
VOR Rwy 23 [D23]
Cycles 1209 and 1210

Incorrect Missed Approach Hold

Jeppesen NavData for cycles 1209 and 1210, effective 23 August 2012 and 20 September 2012 respectively, contain an incorrect missed approach hold on the VOR RWY 23 [D23] at Merignac Airport; Bordeaux, France (LFBD). Inbound course to **ETPAR** should be **166°**.

THEREFORE, USE CAUTION WHEN FLYING THE MISSED APPROACH FOR THE VOR RWY 23 IN CYCLES 1209 AND 1210 NAVDATA.

Revised coding will appear in Jeppesen NavData for cycle 1211, effective 18 October 2012. Until then an entry will appear in the NavData Change Notices, and this Alert will be posted on the Jeppesen Web site: <http://www1.jeppesen.com/company/alerts/aviation-alerts.jsp?region=Western%20Europe%20%26%20Mediterranean>

WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:

Phone: 303-328-4445

E-mail: navdatatechsupport@jeppesen.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. They are distributed to affected ARINC 424 NavData users (avionics companies and other raw data users) and airlines receiving NavData directly from Jeppesen. Alerts are not distributed by Jeppesen to individual airline, business aviation or general aviation pilots, but are available to them on the Jeppesen Web site, www.jeppesen.com. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. Avionics users should consult with their database update service provider for definitive information on whether their system is affected by this Alert.

LFBD 1209 and 1210