



JEPPESEN.
NavData® Alert

!! URGENT !!

Date: 23 September 2011

Subject: South Hill, Virginia
Mecklenburg – Brunswick Regl (KAVC)
RNAV (GPS) Rwy 19 [R19]
Cycle 1110

Incorrect Missed Approach Data

Jeppesen NavData for cycle 1110, effective 22 September 2011, contains incorrect missed approach data for the RNAV (GPS) Rwy 19 [R19] at South Hill; Mecklenburg – Brunswick Regl, Virginia (KAVC). The missed approach coding has an incorrect fix name. The fix DUROC was renamed JODEG.

THEREFORE, USE CAUTION WHEN USING THE MISSED APPROACH FOR THE RNAV (GPS) RWY 19 [R19] AT SOUTH HILL; MECKLENBURG – BRUNSWICK REGL, VIRGINIA (KAVC) IN CYCLE 1110 NAVDATA.

Revised coding will appear in Jeppesen NavData for cycle 1111, effective 20 October 2011. Please refer to the South Hill, Virginia (KAVC) 12-2 chart dated 23 JUL 10, Eff 29 Jul, for valid information. This Alert will be posted on the Jeppesen Web site (<http://www.jeppesen.com/company/alerts/aviation-alerts.jsp?region=United States>)

WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:

Phone: 1-303-328-4445

E-mail: navdatatechsupport@jeppesen.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. They are distributed to affected ARINC 424 NavData users (avionics companies and other raw data users) and airlines receiving NavData directly from Jeppesen. Alerts are not distributed by Jeppesen to individual airline, business aviation or general aviation pilots, but are available to them on the Jeppesen Web site, www.jeppesen.com. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. Avionics users should consult with their database update service provider for definitive information on whether their system is affected by this Alert.

KAVC 1110