



JEPPesen®

NavData® Alert

!! URGENT !!

Date: 24 August 2012

Subject: Shawbury, United Kingdom
Shawbury (EGOS)
Multiple Approach Procedures
Cycle 1209

Outdated Approach Procedures

Jeppesen NavData for cycle 1209, effective 23 August 2012, contains outdated coding on Instrument Approach Procedures at Shawbury Airport, Shawbury, United Kingdom (EGOS).

UK MIL AIRAC Amendment 9/12 was received after the date specified by ICAO for aeronautical information distribution. As a result, changes could not be processed for the follow procedures:

ILS DME Rwy 18 [I18]
COPTER ILS DME Rwy 18 [I18]
COPTER VOR DME Rwy 05 [D05]
COPTER VOR DME Rwy 23 [D23]
COPTER VOR DME Rwy 18 [D18]
COPTER VOR DME Rwy 36 [D36]

THEREFORE, DO NOT USE THE ABOVE INSTRUMENT APPROACH PROCEDURES AT SHAWBURY AIRPORT (EGOS) IN CYCLE 1209 NAVDATA.

Revised coding will appear in Jeppesen NavData for cycle 1210, effective 20 September 2012. Until then an entry will appear in the NavData Change Notices and this Alert will be posted on the Jeppesen Web site:

<http://www1.jeppesen.com/main/corporate/company/alerts/aviation-alerts.jsp?region=Western%20Europe%20%26%20Mediterranean>

WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:

Phone: 303-328-4445

E-mail: navdatatechsupport@jeppesen.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. They are distributed to affected ARINC 424 NavData users (avionics companies and other raw data users) and airlines receiving NavData directly from Jeppesen. Alerts are not distributed by Jeppesen to individual airline, business aviation or general aviation pilots, but are available to them on the Jeppesen Web site, www.jeppesen.com. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. Avionics users should consult with their database update service provider for definitive information on whether their system is affected by this Alert.

EGOS 1209