



JEPPESEN[®]

NavData[®] Alert

!! URGENT !!

Date: 22 June 2012

Subject: Stockholm, Sweden
Arlanda (ESSA)
RNAV SIDs LUMAX 3R [LUMA3R] and TALEK 3R [TALE3R]
Cycle 1207

Incorrect Crossing Altitude

Jeppesen NavData for cycle 1207, effective 28 Jun 2012, contains an incorrect crossing altitude on the LUMAX 3R [LUMA3R] and TALEK 3R [TALE3R] RNAV Standard Instrument Departure Procedures at Arlanda Airport; Stockholm, Sweden (ESSA). The correct crossing altitude at the Arlanda VOR [ARL] as published in NOTAM CL I A0263/12 should read "At or above 2500'".

THEREFORE, EXERCISE CAUTION WHEN SELECTING THE LUMAX 3R [LUMA3R] AND TALEK 3R [TALE3R] RNAV STANDARD INSTRUMENT DEPARTURE PROCEDURES IN CYCLE 1207 NAVDATA.

Revised coding will appear in Jeppesen NavData for cycle 1208, effective 26 Jul 2012. Until then an entry will appear in the NavData Change Notices beginning 29 Jun 2012, and this Alert will be posted on the Jeppesen Web site

(<http://www1.jeppesen.com/company/alerts/aviation-alerts.jsp?region=Western%20Europe%20%26%20Mediterranean>).

WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:

Phone: 303-328-4445

E-mail: navdatatechsupport@jeppesen.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. They are distributed to affected ARINC 424 NavData users (avionics companies and other raw data users) and airlines receiving NavData directly from Jeppesen. Alerts are not distributed by Jeppesen to individual airline, business aviation or general aviation pilots, but are available to them on the Jeppesen Web site, www.jeppesen.com. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. Avionics users should consult with their database update service provider for definitive information on whether their system is affected by this Alert.

ESSA 1207