



JEPPESSEN.

NavData® Alert

!! URGENT !!

Date: 9 October 2012

**Subject: Barranquilla, Colombia
Ernesto Cortissoz (SKBQ)
LOC Rwy 05 [L05]
VOR Rwy 05 [D05 or S05]
Cycle 1211**

Temporary Approach Procedures Revised

Jeppesen NavData for cycle 1211, effective 18 October 2012, contains temporary approaches at Ernesto Cortissoz; Barranquilla, Colombia (SKBQ). Colombia AIP Supplement A28/12 has revised the temporary procedures by raising the altitude at BAQ VOR to 2400' on the temporary LOC Rwy 05 [L05] and the temporary VOR Rwy 05 [D05 or S05] approach procedures.

THEREFORE USE CAUTION WHEN USING THE LOC RWY 05 [L05] AND VOR RWY 05 [D05 or S05] APPROACH PROCEDURES IN NAVDATA CYCLE 1211.

Revised coding will appear in Jeppesen NavData for cycle 1212, effective 15 Nov 2012. Until then an entry will appear in the NavData Change Notices beginning 19 OCT 12, and this Alert will be posted on the Jeppesen Web site (<http://www1.jeppesen.com/company/alerts/aviation-alerts.region=SouthAmerica>).

Please Refer to Jeppesen charts dated 26 OCT 2012 for current information and a Chart Alert is also posted on Jeppesen.com for more information.

**WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO
APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!**

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:

Phone: 1-303-328-4445

E-mail: navdatatechsupport@jeppesen.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. They are distributed to affected ARINC 424 NavData users (avionics companies and other raw data users) and airlines receiving NavData directly from Jeppesen. Alerts are not distributed by Jeppesen to individual airline, business aviation or general aviation pilots, but are available to them on the Jeppesen Web site, www.jeppesen.com. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. Avionics users should consult with their database update service provider for definitive information on whether their system is affected by this Alert.

SKBQ 1211