



JEPPESSEN®

NavData® Alert

!! URGENT !!

Date: 08 Nov 2012
Subject: London, United Kingdom
Gatwick (EGKK)
Departure procedures
Cycle 1212

Incorrect alternative SID coding

Jeppesen NavData for cycle 1212, effective 15 November 2012, contains incorrect alternative SID procedure identifiers and is missing alternative SID procedures at Gatwick airport; London, United Kingdom (EGKK).

Rwy	incorrect NavData	update	correct NavData	Remarks
26L	TIGER 2M [TIGE2M]	up-numbered	TIGER 3M [TIGE3M]	rest unchanged
26R	TIGER 2V [TIGE2V]	renamed	DAGGA 1V [DAGA1V]	rest unchanged
26L	missing SID	New	DAGGA 1M [DAGA1M]	not avbl in cycle 1212 NavData
26R	missing SID	New	TIGER 3V [TIGE3V]	not avbl in cycle 1212 NavData

THEREFORE, USE CAUTION WHEN FLYING ALTERNATIVE SID PROCEDURES FOR RWY 26L/R AT LONDON/GATWICK, UNITED KINGDOM (EGKK) IN CYCLE 1212 NAVDATA.

Revised coding with correct NavData designators and missing SID will appear in Jeppesen NavData for cycle 1213, effective 13 December 2012. Until then, an entry will appear in the NavData Change Notices and this Alert will be posted on the Jeppesen Web site:

<http://www1.jeppesen.com/company/alerts/aviation-alerts.jsp?region=Western%20Europe%20%26%20Mediterranean>

Refer to chart 20-3S dated 9 NOV 12 **Eff 15 Nov** for correct information.

WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:

Phone: 303-328-4445

E-mail: navdatatechsupport@jeppesen.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. They are distributed to affected ARINC 424 NavData users (avionics companies and other raw data users) and airlines receiving NavData directly from Jeppesen. Alerts are not distributed by Jeppesen to individual airline, business aviation or general aviation pilots, but are available to them on the Jeppesen Web site, www.jeppesen.com. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. Avionics users should consult with their database update service provider for definitive information on whether their system is affected by this Alert.

EGKK 1212