

**JEPPESEN**
NavData® Alert

!! URGENT !!

Date: 13 May 2008

Subject: Aspen, Colorado
Pitkin CO/Sardy Airport (KASE)
IPKN Localizer
Cycle 0805

Incorrect Bearing on Localizer Record

Jeppesen NavData for cycle 0805, effective 8 May 2008, contains an incorrect localizer bearing on 'IPKN' Localizer at Aspen-Pitkin CO/Sardy Airport; Aspen, Colorado (KASE). The correct localizer bearing for the 'IPKN' Localizer (PI record) at KASE should be 300°.

THEREFORE, DO NOT USE THE 'IPKN' LOCALIZER RECORD IN JEPPESEN 0805 NAVDATA.

Revised coding will appear in Jeppesen NavData for cycle 0806, effective 5 June 2008. Until then an entry will appear in the NavData Change Notices beginning 30 May 2008, and this Alert will be posted on the Jeppesen Web site (www.jeppesen.com, click on Aviation Resources, On-line Publications, NavData NOTAMs/Alerts).

WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:

Phone: 303-328-4445 Fax: 303-328-4122

E-mail: navdatatechsupport@jeppesen.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. They are distributed to affected ARINC 424 NavData users (avionics companies and other raw data users) and airlines receiving NavData directly from Jeppesen. Alerts are not distributed by Jeppesen to individual airline, business aviation or general aviation pilots, but are available to them on the Jeppesen Web site, www.jeppesen.com. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. Avionics users should consult with their database update service provider for definitive information on whether their system is affected by this Alert.