



# **JEPPESSEN.**

## **NavData® Alert**

### **!! URGENT !!**

**Date:** 15 October 2009

**Subject:** Greensboro, North Carolina  
Piedmont Triad Intl (KGSO)  
ILS or LOC Rwy 5R [I05R]  
Cycle 0911

***Invalid turn direction on missed approach***

Jeppesen NavData for cycle 0911, effective 22 October 2009, contains invalid missed approach coding for ILS or LOC Rwy 5R [I05R] at Piedmont Triad Intl; Greensboro, North Carolina (KGSO). The missed approach contains a right turn to intercept GSO R-108 to KIMES intersection. The 139 degree heading to intercept GSO R-108 is a 31 degree intercept and does not require a turn direction.

**THEREFORE, EXERCISE CAUTION WHEN USING THE MISSED APPROACH FOR ILS OR LOC RWY 5R [I05R] IN CYCLE 0911 NAVDATA.**

Revised coding will appear in Jeppesen NavData for cycle 0912, effective 19 November 2009. Until then an entry will appear in the NavData Change Notices beginning 23 OCT 09, and this Alert will be posted on the Jeppesen Web site (<http://www.jeppesen.com/company/alerts/aviation-alerts.jsp?region=United%20States>). Please refer to the Greensboro, North Carolina (KGSO) 11-2 chart dated 16 OCT 09 (effective 22 OCT 09) for valid information.

**WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!**

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:

Phone: 303-328-4445

E-mail: [navdatatechsupport@jeppesen.com](mailto:navdatatechsupport@jeppesen.com)

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. They are distributed to affected ARINC 424 NavData users (avionics companies and other raw data users) and airlines receiving NavData directly from Jeppesen. Alerts are not distributed by Jeppesen to individual airline, business aviation or general aviation pilots, but are available to them on the Jeppesen Web site, [www.jeppesen.com](http://www.jeppesen.com). Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. Avionics users should consult with their database update service provider for definitive information on whether their system is affected by this Alert.

KGSO 0911