



## !! URGENT !!

**Date:** 26 September 2008

**Subject:** Leon, Spain  
Leon Airport (LELN)  
Departures  
RATAS TWO GOLF [RATA2G]  
VEDER TWO GOLF [VEDE2G]  
ZAMORA TWO GOLF [ZMR2G]  
Approaches  
ILS Rwy 23 [I23]  
VOR DME Rwy 23 [D23]  
Cycle 0810

*Procedures postponed until 9 October 2008*

Jeppesen NavData for cycle 0810, effective 25 September 2008, contains changes introduced in AIRAC Amendment 09/08, effective 25 September 2008. **These changes have been postponed until 9 October 2008** by Class I NOTAM A6991/08.

**THEREFORE, UNTIL 9 OCTOBER 2008, DO NOT USE DEPARTURE PROCEDURES RATAS TWO GOLF [RATA2G], VEDER TWO GOLF [VEDE2G], ZAMORA TWO GOLF [ZMR2G], AS WELL AS APPROACH PROCEDURES ILS RWY 23 [I23], VOR DME RWY 23 [D23] AT LEON, SPAIN, LEON AIRPORT (LELN) THAT ARE CONTAINED IN CYCLE 0810 NAVDATA.**

Correct coding will be available in Jeppesen NavData for cycle 0810, effective 25 September 2008, but will not be usable until the postponement date of 9 October 2008. This Alert will be posted on the Jeppesen Web site ([www.jeppesen.com](http://www.jeppesen.com), under Online Publications, then click on Notices / Alerts, NavData Alerts and Notices). Until 9 October 2008 valid charts, dated 3 OCT 08, will be posted on the Jeppesen Web site ([www.jeppesen.com](http://www.jeppesen.com) under Online Publications, then click on Notices / Alerts, HubWatch).

**WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!**

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:

Phone: 303-328-4445 Fax: 303-328-4122

E-mail: [navdatatechsupport@jeppesen.com](mailto:navdatatechsupport@jeppesen.com)

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. They are distributed to affected ARINC 424 NavData users (avionics companies and other raw data users) and airlines receiving NavData directly from Jeppesen. Alerts are not distributed by Jeppesen to individual airline, business aviation or general aviation pilots, but are available to them on the Jeppesen Web site, [www.jeppesen.com](http://www.jeppesen.com). Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. Avionics users should consult with their database update service provider for definitive information on whether their system is affected by this Alert.

LELN 0810