



## **!! URGENT !!**

**Date:** 26 February 2010

**Subject:** Manaus, Brazil  
Eduardo Gomes Intl (SBEG)  
DADRA 1 Departure [DADRA1]  
Cycle 1003

### ***Incorrect Initial Departure Heading***

Jeppesen NavData for cycle1003, effective 11 March 2010, contains an incorrect initial heading on the Rwy 28 Transition for the DADRA 1 [DADRA1] Departure at Eduardo Gomes Intl; Manaus, Brazil (SBEG). The correct initial heading for the Rwy 28 Transition is 284°.

**THEREFORE, DO NOT USE THE RWY 28 TRANSITION IN THE DADRA 1 DEPARTURE PROCEDURE [DADRA1] IN CYCLE 1003 NAVDATA.**

Revised coding will appear in Jeppesen NavData for cycle 1004, effective 08 April 2010. Until then an entry will appear in the NavData Change Notices beginning 12 MAR 10, and this Alert will be posted on the Jeppesen Web site (<http://www.jeppesen.com/company/alerts/aviation-alerts.jsp?region=South%20America>). Please refer to the Manaus, Brazil (SBEG) 20-3A chart dated 12 DEC 08 for valid information.

**WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!**

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:

Phone: 303-328-4445

E-mail: [navdatatechsupport@jeppesen.com](mailto:navdatatechsupport@jeppesen.com)

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. They are distributed to affected ARINC 424 NavData users (avionics companies and other raw data users) and airlines receiving NavData directly from Jeppesen. Alerts are not distributed by Jeppesen to individual airline, business aviation or general aviation pilots, but are available to them on the Jeppesen Web site, [www.jeppesen.com](http://www.jeppesen.com). Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. Avionics users should consult with their database update service provider for definitive information on whether their system is affected by this Alert.

SBEG 1003