



JEPPESSEN.

NavData® Alert

!! URGENT !!

Date: 10 December 2012

Subject: Barranquilla, Colombia
Ernesto Cortissoz (SKBQ)
ILS Y Rwy 05 [I05-Y]
ILS Z Rwy 05 [I05-Z]
VOR Rwy 05 [D05 or S05]
Cycles 1212 1213

Approach Procedures suspended

Jeppesen NavData for cycles 1212 and 1213, effective 15 November 2012 and 13 December respectively, contains suspended approaches at Ernesto Cortissoz; Barranquilla, Colombia (SKBQ). Colombia AIP Supplement A34/12 suspended all existing approaches into Rwy 05 Until 31 January 2013. Colombia AIP Supplement A34/12 also established Temporary procedures LOC Rwy 05 and VOR Rwy 05 for use until 31 January 2013.

THEREFORE DO NOT USE THE FOLLOWING APPROACH PROCEDURES IN NAVDATA CYCLES 1212 and 1213.

Procedure Ident
ILS Y Rwy 05 [I05-Y]
ILS Z Rwy 05 [I05-Z]
VOR Rwy 05 [D05 or S05]

The Temporary procedures will appear in Jeppesen NavData for cycles 1212 and 1213. Until then an entry will appear in the NavData Change Notices and this Alert will be posted on the Jeppesen Web site (<http://www1.jeppesen.com/company/alerts/aviation-alerts.region=SouthAmerica>).

WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:

Phone: 1-303-328-4445

E-mail: navdatatechsupport@jeppesen.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. They are distributed to affected ARINC 424 NavData users (avionics companies and other raw data users) and airlines receiving NavData directly from Jeppesen. Alerts are not distributed by Jeppesen to individual airline, business aviation or general aviation pilots, but are available to them on the Jeppesen Web site, www.jeppesen.com. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. Avionics users should consult with their database update service provider for definitive information on whether their system is affected by this Alert.

SKBQ 1212 1213