



# JEPPESEN.

## NavData® Alert

### !! URGENT !!

**Date:** 2 May 2012

**Subject:** Hanoi, Vietnam  
 Noi Bai Intl (VVNB)  
 Approach, Arrival, and Departure Procedures  
 Cycle 1205

***Revised Approach, Arrival, and Departure Procedures***

Jeppesen NavData Approach, Arrival, and Departure at Hanoi, Vietnam – Noi Bai Intl Airport (VVNB) will contain out of date information for cycle 1205 NavData Effective, 3 May 2012. Vietnam AIP Supplement A04/12 was received after the date specified by ICAO for aeronautical information distribution. As a result, changes to the Approaches, Arrivals, and Departures listed below could not be processed for cycle 1205 NavData, Effective 3 May 2012.

**THEREFORE, DO NOT USE CYCLE 1205 NAVDATA FOR THE PROCEDURES INDICATED AS PROCEDURE UNSABLE, OR EXERCISE CAUTION BASED ON THE FOLLOWING:**

**Arrivals:**

Procedures	Runway	Changes
CAB ONE ALPHA [CAB1A]	11 L/R	Procedure Unusable
LAOCAI ONE ALPHA [LAO1A]	11 L/R	Ident changed to LAOCAI TWO ALPHA [LACA2A]
MEOVA TWO ALPHA [MEO2A]	11 L/R	Ident changed to TAMDA THREE ALPHA [TAMD3A]
MOCCHAU ONE ALPHA [MC1A]	11 L/R	No changes
NAMHA ONE ALPHA [NAH1A]	11 L/R	No changes
NASAN ONE ALPHA [NAS1A]	11 L/R	Ident changed to NASAN TWO ALPHA [BQ2A]
TEBAK ONE ALPHA [TEA1A]	11 L/R	Procedure Unusable
CAB ONE BRAVO [CAB1B]	29 L/R	Procedure Unusable
LAOCAI ONE BRAVO [LAO1B]	29 L/R	Ident changed to LAOCAI TWO BRAVO [LACA2B]
MOCCHAU ONE BRAVO [MC1B]	29 L/R	No changes
NAMHA ONE BRAVO [NAH1B]	29 L/R	No changes
NASAN ONE BRAVO [NAS1B]	29 L/R	Ident changed to NASAN TWO BRAVO [BQ2B]
TEBAK ONE BRAVO [TEA1B]	29 L/R	Procedure Unusable
CAB ONE CHARLIE [CAB1C]	11L / 29R	Procedure Unusable
LAOCAI ONE BRAVO [LAO1B]	11L / 29R	Ident changed to LAOCAI TWO CHARLIE [LACA2C]
MOCCHAU ONE CHARLIE [MC1C]	11L / 29R	No changes
NAMHA ONE CHARLIE [NAH1C]	11L / 29R	No changes
NASAN ONE CHARLIE [NAS1C]	11L / 29R	Ident changed to NASAN TWO CHARLIE [BQ2C]
TEBAK ONE CHARLIE [TEA1C]	11L / 29R	Procedure Unusable

**Departures:**

Procedures	Runway	Changes
CATBI ONE ALPHA [CAT1B]	11 L/R	Procedure Unusable
HAKAO ONE ALPHA [HAK1A]	11 L/R	Ident changed to HAKAO TWO ALPHA [HAKA2A]

HAKAO ONE CHARLIE [HAK1C]	11 L/R	Ident changed to HAKAO TWO CHARLIE [HAKA2C]
HUVAN ONE ALPHA [HUN1A]	11 L/R	Ident changed to HUVAN TWO ALPHA [HUVA2A]
HUVAN ONE CHARLIE [HUN1C]	11 L/R	Ident changed to HUVAN TWO CHARLIE [HUVA2C]
TONGA ONE ALPHA [TON1A]	11 L/R	Ident changed to TONGA TWO ALPHA [TONG2A]
TRANA ONE [TRA1]	11 L/R	Ident changed to TRANA TWO [TRAN2A]
VINHA ONE ALPHA [VIN1A]	11 L/R	Ident changed to VINHA TWO ALPHA [VINH2A]
VINHA ONE CHARLIE [VIN1C]	11 L/R	Ident changed to VINHA TWO CHARLIE [VINH2C]
VITRA ONE ALPHA [VIT1A]	11 L/R	Ident changed to VITRA TWO ALPHA [VITR2A]
CATBI ONE BRAVO [CAT1B]	29 L/R	Procedure Unusable
HAKAO ONE BRAVO [HAK1B]	29 L/R	Ident changed to HAKAO TWO BRAVO [HAKA2B]
HUVAN ONE BRAVO [HUN1B]	29 L/R	Ident changed to HUVAN TWO BRAVO [HUVA2B]
TONGA ONE BRAVO [TON1B]	29 L/R	Ident changed to TONGA TWO BRAVO [TONG2B]
VINHA ONE BRAVO [VIN1B]	29 L/R	Ident changed to VINHA TWO BRAVO [VINH2B]
VITRA ONE BRAVO [VIT1B]	29 L/R	Ident changed to VITRA TWO BRAVO [VITR2B]
TAMDA TWO ALPHA [TAM2A]	11 L/R, 29 L/R	Ident changed to TAMDA THREE ALPHA [TAMD3A]
TAMDA TWO BRAVO [TAM2B]	11 L/R, 29 L/R	Ident changed to TAMDA THREE BRAVO [TAMD3B]

### Approach Procedures:

Procedure	Changes
VOR DME ILS Rwy 11L [I11L]	Ident changed to ILS Z Rwy 11L [I11LZ]
VOR DME ILS Rwy 11R [I11R]	Ident changed to ILS Y Rwy 11R [I11RY]
VOR DME Rwy 11L [D11L] procedure unusable	Ident changed to VOR Y Rwy 11L [D11LY] or [S11LY]
VOR DME Rwy 11R [D11R] procedure unusable	Ident changed to VOR Y Rwy 11R [D11RY] or [S11RY]
VOR DME Rwy 29L [D29L] procedure unusable	Ident changed to VOR Rwy 29L [D29L] or [S29L]
VOR DME Rwy 29R [29R] procedure unusable	Ident changed to VOR Rwy 29R [D29R] or [S29R]

Revised coding will appear in Jeppesen NavData for cycle 1206, effective 31 May 2012. Until then an entry will appear in the NavData Change Notices beginning 10 May 12 and this Alert will be posted on the Jeppesen Web site (<http://jeppesen.com/company/alerts/aviation-alerts.jsp>)

## **WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!**

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:

Phone: 1-303-328-4445

E-mail: [navdatatechsupport@jeppesen.com](mailto:navdatatechsupport@jeppesen.com)

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. They are distributed to affected ARINC 424 NavData users (avionics companies and other raw data users) and airlines receiving NavData directly from Jeppesen. Alerts are not distributed by Jeppesen to individual airline, business aviation or general aviation pilots, but are available to them on the Jeppesen Web site, [www.jeppesen.com](http://www.jeppesen.com). Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. Avionics users should consult with their database update service provider for definitive information on whether their system is affected by this Alert.