



JEPPESEN[®]

NavData[®] Alert

!! URGENT !!

Date: 5 February 2009

Subject: Labuan I, Malaysia
Labuan Airport (WBKL)
Arrival, Departure and Approach Procedures
Cycles 0901 & 0902

Arrival, Departure and Approach Procedures Suspended

Jeppesen NavData for cycles 0901 and 0902, effective 15 January and 12 February 2009, respectively, contain Arrival, Departure, and Approach Procedure information for Labuan Airport; Labuan, Malaysia (WBKL) in accordance with AIP Supplement 38/2008, effective 15 January 2009. However, the implementation of AIP Supplement 38/2008 has been postponed until 01 May 2009 via Class 1 NOTAM D0039/09.

THEREFORE, DO NOT USE THE ARRIVAL, DEPARTURE AND APPROACH PROCEDURES LISTED BELOW IN CYCLES 0901 AND 0902 NAVDATA FOR LABUAN AIRPORT (WBKL):

All Arrival Procedures
All Departures Procedures
ILS RWY 14 [I14]
VOR DME RWY 14 [D14]
VOR DME RWY 32 [D32]
VOR RWY 14 [S14]
NDB RWY 14 [N14]

The affected procedures will be removed from Jeppesen NavData for cycle 0903, effective 12 March 2009.

THE FOLLOWING PROCEDURES ARE USABLE IN CYCLE 0901 AND 0902 NAVDATA:

VOR RWY 32 [S32]
LOCATOR RWY 32 [N32]

Until 12 March 2009, an entry will appear in the NavData Change Notices beginning 13 FEB 09, and this Alert will be posted on the Jeppesen Web site (<http://www.jeppesen.com/company/alerts/alerts.jsp>).

For the list of affected Charted Procedures see the respective HubWatch Notice posted on the Publications page on the Jeppesen Web site (<http://www.jeppesen.com/company/publications/publications.jsp>).

WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:
Phone: 303-328-4445 E-mail: navdatatechsupport@jeppesen.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. They are distributed to affected ARINC 424 NavData users (avionics companies and other raw data users) and airlines receiving NavData directly from Jeppesen. Alerts are not distributed by Jeppesen to individual airline, business aviation or general aviation pilots, but are available to them on the Jeppesen Web site, www.jeppesen.com. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. Avionics users should consult with their database update service provider for definitive information on whether their system is affected by this Alert.