



!! URGENT !!

Date: 14 March 2008

Subject: Shanghai, China
ZSPD: All procedures
ZSSS: JTN 12D [JTN12D], PK 12D [PK12D], PK 14D [PK14D]
Cycle 0803

SHANGHAI, CHINA AIRPORTS HONGQIAO (ZSSS) & PUDONG (ZSPD) AIRPORTS

POSTPONEMENT OF PROCEDURE CHANGES

ATTENTION NAVDATA CUSTOMERS:

The Chinese Civil Authority has postponed the implementation of procedure changes for ZSSS and ZSPD airports originally scheduled to be effective March 13, 2008. (Reference: Chinese NOTAMS A1648/08 and A1649/08 dated March 12, 2008.)

SID procedures for Shanghai Hongqiao (ZSSS) depicted on Jeppesen Chart 10-3D dated 26 OCT 07 effective before March 13, 2008 will remain valid until at least March 25, 2008 as well. (Reference procedures: JTN 11A, PK 12A, PK 14A.)

- **0803 ZSSS SID NavData idents [JTN12D], [PK12D] and [PK14D] are not usable until at least March 25, 2008.** Confirm procedure effectivity prior to use.

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:

Phone: 303-328-4445 Fax: 303-328-4122

E-mail: navdatatechsupport@jeppesen.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. They are distributed to affected ARINC 424 NavData users (avionics companies and other raw data users) and airlines receiving NavData directly from Jeppesen. Alerts are not distributed by Jeppesen to individual airline, business aviation or general aviation pilots, but are available to them on the Jeppesen Web site, www.jeppesen.com. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. Avionics users should consult with their database update service provider for definitive information on whether their system is affected by this Alert.

ZSPD-ZSSS

All procedures for Shanghai Pudong (ZSPD) effective before March 13, 2008 will remain valid until at least March 25, 2008.

- **0803 ZSPD NavData procedures are not usable until at least March 25, 2008.** Confirm procedure effectivity prior to use.

Jeppesen Airway Manual charts had already been updated and issued in Airway Manual chart revisions dated 29 FEB and 07 MAR with the effective date of March 13.

Unfortunately the procedure changes had been issued to customers before the postponement NOTAM was issued and received. Due to the circumstances we were not able to remove the affected charts or procedures from your latest Airway Manual chart revision or NavData update.

Pilots are advised to retain the old (still valid) versions of the charts for these airports until the new effective date of 25 March, or until advised otherwise. In case your charts have already been updated and the old charts are no longer available, copies of the old (still valid) charts are available on our website through the link listed below.

- The NavData coding contained in update Cycle 0803 is NOT USABLE until at least March 25, 2008 for these procedures referenced at these two airports Pilots are advised to contact ATC for instructions and/or refer to the applicable charts as indicated above.

<http://www.jeppesen.com/wlcs/index.jsp?section=resources&content=hubwatch.jsp>

IMPORTANT NOTE: Operators and flight crews are urged to monitor NOTAMs for the current status of these procedures and the new effective date for implementation of procedural changes.

WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:

Phone: 303-328-4445 Fax: 303-328-4122

E-mail: navdatatechsupport@jeppesen.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. They are distributed to affected ARINC 424 NavData users (avionics companies and other raw data users) and airlines receiving NavData directly from Jeppesen. Alerts are not distributed by Jeppesen to individual airline, business aviation or general aviation pilots, but are available to them on the Jeppesen Web site, www.jeppesen.com. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. Avionics users should consult with their database update service provider for definitive information on whether their system is affected by this Alert.

ZSPD-ZSSS