



## AVIATION SERVICE DOCUMENT NOTIFICATION

**TO:** Registered Garmin G500 Owner/Operators  
**DATE:** January 22, 2013  
**SUBJECT:** This communication is intended to inform Garmin aviation customers of forthcoming service document Software Service Bulletin 1303 G500 AML STC update for GDU 620 Software Version 6.11, GRS 77 Software Version 3.03, and GDC 74 Software Version 3.09.

### COMPLIANCE

**Mandatory**

### PURPOSE

This Service Bulletin announces an update to the G500 AML STC (SA02015SE-D) to include GDU 620 Software Version 6.11, GRS 77 Ahrs Software Version 3.03, and GDC 74 ADC Software Version 3.09.

### PRODUCTS AFFECTED

G500 systems installed in accordance with the G500 AML STC (SA02015SE-D).

### DESCRIPTION

This software service bulletin describes the process for upgrading software for:

System	LRU	Software P/N	New Software Version
G500	GDU 620 Display	006-B1071-4B	6.11
	GRS 77 Ahrs	006-B0223-23	3.03
	GDC 74 ADC	006-B0261-19	3.09

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.