



SERVICE ALERT

NO.: 0801

TO: All Garmin Aviation Service Centers
DATE: 25 January 2008
SUBJECT: Supplemental Data Cards Should Not Be Used To Load Jeppesen NavData

AFFECTED PRODUCTS

All G1000 Integrated Flight Deck systems.

DESCRIPTION

Some G1000 Pilot's Guides suggest that Jeppesen NavData can be loaded onto Garmin supplemental data cards. Due to issues encountered with loading Jeppesen NavData database information onto Garmin 010-00330-41 or 010-00330-42 supplemental data cards, Garmin no longer recommends this procedure.

NOTE

Loading Jeppesen Chartview data onto these supplemental data cards remains acceptable.

RESOLUTION

Load the Jeppesen NavData database information only onto blank SD cards for transferring data to GDU's.

Garmin is in the process of removing the statement that suggests loading NavData onto supplemental data cards from all G1000 Pilot's Guide documents.

NOTE

Garmin recommends the use of SanDisk SD cards to load Jeppesen data. If loading problems occur when using another brand of card, replace the card with a SanDisk card and reattempt the load.

© Copyright 2008
Garmin Ltd. or its subsidiaries
All Rights Reserved

Except as expressly provided herein, no part of this document may be reproduced, copied, transmitted, disseminated, downloaded or stored in any storage medium, for any purpose without the express prior written consent of Garmin. Garmin hereby grants permission to download a single copy of this document and of any revision to this document onto a hard drive or other electronic storage medium to be viewed and to print one copy of this document or of any revision hereto, provided that such electronic or printed copy of this document or revision must contain the complete text of this copyright notice and provided further that any unauthorized commercial distribution of this document or any revision hereto is strictly prohibited.